

From: [Thomas, Mark J.](#)
To: [Bernier, Roberto](#)
Subject: RE: 2 Sept 2017 -- ASPECT Update 11 -- 1500
Date: Saturday, September 2, 2017 3:06:43 PM

The trailers on the ne side. It appears that three are leaking. Some has discharged to the south and some to the north. Are you seeing any emission from the ground. We are not seeing anything from the air?

Mark Thomas, PhD
ASPECT Program Manager
Field Operations Branch
CBRN Consequence Management Advisory Division
EPA Office of Emergency Management
11201 Renner Blvd
Lenexa, KS 66219
Office: 913-551-5018
Cell: 513-675-4753

From: Bernier, Roberto
Sent: Saturday, September 02, 2017 3:05 PM
To: Thomas, Mark J. ; ASPECT_Harvey
Subject: RE: 2 Sept 2017 -- ASPECT Update 11 -- 1500
Which trailers? The remaining 6 in the NE corner of facility?

From: Thomas, Mark J.
Sent: Saturday, September 02, 2017 3:03 PM
To: ASPECT_Harvey <ASPECT_Harvey@epa.gov>
Subject: 2 Sept 2017 -- ASPECT Update 11 -- 1500
The aircraft is detecting multiple hits of peroxide. The winds appear to be very light but most detections are south and/or west of the trailers. Levels are not high again near the detection limit of the system or about 5 ppm.
Mark Thomas, PhD
ASPECT Program Manager
Field Operations Branch
CBRN Consequence Management Advisory Division
EPA Office of Emergency Management
11201 Renner Blvd
Lenexa, KS 66219
Office: 913-551-5018
Cell: 513-675-4753